



**GLOBAL TURBINE  
COMPONENT TECHNOLOGIES LLC**

REPAIR TEARDOWN INSPECTION REPORT  
FAA REPAIR STATION NUMBER G1UR437Y

**JOB NUMBER 34548**

**SER NUMBER 002463708971**

**NOMENCLATURE: FIRE SHIELD**

**ENG MODEL: LF 507-1F**

**INCOMING PART NO 2-263-410-05**

**OUTGOING PART NO: 2-263-410-05**

**CUSTOMER: 10192 ANSETT AIRCRAFT SPARES**

**PO NUMBER: U50006827**

**LINE ITEM 3**

**TECH DATA: LF 507-1F E.M. 507F.1 Rev. 5 Dated 9-30-1999**

**STD PCT MAN: SPM 286.2 (REV. 13,**

**CUSTOMER REQUIREMENTS / REMARKS:**

**OVERHAUL.**

**REQD REPAIRS:**

**REPAIRS -02, -03, & SP R401.**

**REPAIR TEARDOWN:**

**Section 72-41-13: Repair -02, Repair cracking in parent metal & -03, Repair dents and distortion. SP R401, Repair nicks and burrs IAW SPM 286.2 (Rev. 13, dated Mar. 31, 2006), Section 70-25-01, FULL DETAILS OF WORK CARRIED OUT PER JOB ORDER NO: 34548.**

**DETAILS REQUIRED:**

**REPAIR / RELEASE ORDER :**

**DATE: 5/16/2012**

**INSPECTOR: Timothy D. Cawthra**

**FORM NUMBER GT5209A / AUTOMATED**

Honeywell

Honeywell



# GLOBAL TURBINE COMPONENT TECHNOLOGIES LLC

125 South Satellite Rd., South Windsor CT 06074. FAA Repair Station G1UR437Y  
Phone 860-528-4722 Fax 860-528-0827

## REPORT OF WORK PERFORMED DURING COMPONENT REPAIR / OVERHAUL

GLOBAL TURBINE JOB NUMBER: 34548

NOMENCLATURE: FIRE SHIELD

PART NUMBER 2-263-410-05

SERIAL NUMBER 002463708971

This component was repaired / overhauled and inspected in accordance with 10192 ANSETT AIRCRAFT SPARES purchase order number U50006827 Per LF 507-1F E.M. 507F.1 Rev. 5 Dated 9-30-1999

### THE FOLLOWING REPAIRS WERE PERFORMED TO MAKE SERVICEABLE:

Section 72-41-13: Repair -02, Repair cracking in parent metal & -03, Repair dents and distortion. SP R401, Repair nicks and burrs IAW SPM 286.2 (Rev. 13, dated Mar. 31, 2006), Section 70-25-01. FULL DETAILS OF WORK CARRIED OUT PER JOB ORDER NO: 34548.

### DETAILS AND OR MATERIALS REQUIRED FOR COMPONENT COMPLETION

DATE : 5/22/2012 INSPECTOR Thomas L. Fielding

Honeywell

Honeywell

Honeywell