



Component Shop Findings Report

Sales Ord Nbr: 9001685051110000
FFFC: 228040000
S/N: 426
MPN: 822-0006-103
Mod Level:
FTN/Batch: H18622
Prime Shop: 351
Serviceable Date: 06/13/2018

Customer Name: HOAT HONEYWELL AEROSPACE TRADI
Incoming Mfr P/N: 822-0006-103
Incoming Serial No.: 426
Incoming Mod Level:
Quantity: 001
Part Description: COMPUTER, A/P FLT DIRECTOR

Shop Order Number: OI5749 PMO Number: 000044317002 Work Order: 96176 Visit: 00

Shop Findings: PIF=NTF. UNIT SENT TO SHOP FOR BENCH TESTING. REAR CONNECTOR COVERS MISSING. NO TROUBLE FOUND DURING TESTING. NO RECENT INTERNAL FAULTS STORED IN MEMORY.

Corrective Actions: RETURN TO SERVICE CHECKS GOOD IAW OEM CMM 22-12-70, REV 28. REPLACED CONNECTOR COVERS.

Engineering Authorizations C/W:

Shop RFR Code: 02 SCHEDULED REMOVAL - NO TROUBLE
Disp Code: 02 NOT N WRNTY,CHECKED
Status/Work: TESTED

Mechanic: D.CHERRY
M 701623 06/13/2018

PRINTED: 06/13/18



Component Shop Findings Report

Sales Ord Nbr: 9001685051110000
FFFC: 228040000
S/N: 426
MPN: 822-0006-103
Mod Level:
FTN/Batch: H18622
Prime Shop: 351
Serviceable Date: 06/13/2018

Shop Order Number: OI5749

PMO Number: 000044317002

PAGE: 1

Parts Replaced This Visit:

Qty	Part Number	Description	FTN/Batch	Reason Replaced
-----	-------------	-------------	-----------	-----------------

NO MATERIALS USED FOR THIS ORDER

Honeywell