

Workshop Report

61506524



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No. 20012600 00000001

Work Order/Contract/Invoice 61506524

Description ACTUATOR A/P AL/ELEV.

Responsible Workshop 33445050

Modification Status according to Mod-Label

See Unit Mod-Label if equipped

Name 419870, Marco Brandt

Date (dd mm yy) 03 Sep 2018

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

Customer Order No. 4208122524

Part. No. as received 158300-101

Serial No. as received 9773

Part No. as dispatched 158300-101

Serial No. as dispatched 9773

Reason for removal UNKNOWN

Findings MAIN CONNECTOR SOAKED WITH FLUID.

Action
MAIN CONNECTOR REPLACED AND POTTING COMPOUND RENEWED LVDT READJUSTED.
AUTOPILOT ACTUATOR ASSY REPAIRED AND TESTED.
NOTE: THIS COMPONENT SHOWS SERVICE RELATED WEARMARKS. THESE WEARMARKS HAVE NEITHER FUNCTIONAL NOR TECHNICAL OBJECTIONS.