



Component Shop Findings Report

Sales Ord Nbr: 9001738700110000
FFFC: 345050010
S/N: 13866
MPN: 1500-2310-001
Mod Level:
FTN/Batch: H26148
Prime Shop: 351
Serviceable Date: 09/18/2018

Customer Name: HOAT HONEYWELL AEROSPACE TRADI
Incoming Mfr P/N: 1500-2310-001
Incoming Serial No.: 13866
Incoming Mod Level:
Quantity: 001
Part Description: COMBINER, COMBINER, SYS IN

Shop Order Number: OQ9878 PMO Number: 000044393772 Work Order: 96176 Visit: 00
Shop Findings: PI-NDN AMBIENT LIGHT SENSOR LOW

Corrective Actions: WORKED WITH REFERENCE TO OEM CMM 34-36-14 REV.7 9/9/11 ADJUSTED A
MBIEMT LIGHT SENSOR

Engineering Authorizations C/W:

Shop RFR Code: 04 UNSKD RMVL - REPORTED TROUBLE FOUND
Disp Code: 01 NOT N WRNTY, REPAIRED
Status/Work: REPAIRED

Mechanic: M.HENNESSEE
M 416339 09/18/2018

PRINTED: 09/18/18



Component Shop Findings Report

Sales Ord Nbr: 9001738700110000
FFFC: 345050010
S/N: 13866
MPN: 1500-2310-001
Mod Level:
FTN/Batch: H26148
Prime Shop: 351
Serviceable Date: 09/18/2018

Shop Order Number: OQ9878

PMO Number: 000044393772

PAGE: 1

Parts Replaced This Visit:

Qty	Part Number	Description	FTN/Batch	Reason Replaced
-----	-------------	-------------	-----------	-----------------

NO MATERIALS USED FOR THIS ORDER

Honeywell