



Teardown Report

WO # : W351176	R.O. # : 3502496620E	TSN :	CSN :	Out Date : 09/29/2017
Customer : HONEYWELL CO..	Desc. : DOOR AY	TSO : UNK	CSO :	Resp : AL4
Mfg P/N : 112N6101-2	S/N : NSN2	TSR : UNK	CSR :	Dept : 1160
Org. P/N : 112N6101-2	Org. S/N : NSN2	TSI :	CSI :	Last WO# :
Mfg Name : BOEING CO	Spec # :	FH :	FC :	Last Resp :

Malfunction : NONE GIVEN

Instructions : REPAIR C/W SPOC 006

Preliminary (Incoming) Inspection : 112N6101-2

EXTRA PART

ARTICLE WAS RECEIVED IN POOR CONDITION. No S/N on article, will assign S/N NSN2 which is stated on RO. ARTICLE WAS RECEIVED WITH EXTRA PART. EXTRA PART WILL BE RETURNED TO CUSTOMER.

Preliminary Functional Test :

Preliminary Functional test NA

Teardown And Inspection Discrepancies Per: BOEING CO, CMM 28-11-07, REV 35

- 1/55, SEAL, Worn.
- 1/1E, DOOR AY, Worn Finish.
- All exposed Seal devices require replacement.
- All other exposed parts require inspection of defects/damage.

Corrective Action For Previous Discrepancies:

1. P-Replaced, .
2. H-Refinished, .
3. Replaced all exposed Seal devices as required.
4. All other exposed parts were inspected and found serviceable.

Functional Test Results Per : SEE ABOVE REFERENCE

Not Applicable

Final Inspection Status :

This article has been repaired, inspected and found airworthy. Article is approved for return to service.


Technician

ADAM LOWTHER

Supervisor

DOUGLAS FREER

Inspection



KENNETH WHIPPLE

Honeywell Honeywell