

SERVICE REPORT

HAT - Phoenix

800-601-3099 (T) 602-822-9194 (F)

SR NUMBER: 5012020402		331450273	FAA: RN3R821L	EASA: 145.4534
PO: 8193503	CUSTOMER PART NUMBER:		CONTRACT NUMBER:	
DATE REJECTED: 15 FEB 2018	DATE RECEIVED: 15 FEB 2018		DATE COMPLETED: 20 FEB 2018	
A/C TYPE: UNK	A/C TAIL NUMBER:		A/C SERIAL NUMBER:	
PACKING STATUS: No	SEALS INTACT: None		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: Spex Core				
PART NUMBER	AS RECEIVED: 4077880-908	AS RELEASED: 4077880-908		
DESCRIPTION:	CONTROL DISPLAY UNIT-MULTIPURPOSE,		CONTROL DISPLAY UNIT-MULTIPURPOSE,	
SERIAL NUMBER	01454884	01454884		
UID(MFR/SPL PNO SER/UCN)	58960 01454884	58960 01454884		
HW MOD STATUS:	A,B,C,D,E,F,H	As received Plus J		
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Failure Not Related to Rejection			ESTIMATE SUPPLIED: No	
PRIMARY SHOP FINDING: Hardware Fault Found			WARRANTY:	
TYPE OF SERVICE: REPAIRED/Modified			TECHNICIAN: Carl Stephenson	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 34-61-57/Rev 11/Rev Date 03 JAN 2017; Service Bulletins: 4077880-34-0021/Rev 0/Rev Date 04 MAY 2015; Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

HAT - Phoenix

800-601-3099 (T) 602-822-9194 (F)

SR NUMBER: 5012020402		FAA: RN3R821L	EASA: 145.4534
PO: 8193503	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
 CMM/Eng Documentation:
 Service Bulletins:
 Customer Manuals/Documentation:

Work performed / Comments to Customer
 Found Keyboard was very worn and has sticky keys, replaced with one from rotatable stock.

"Honeywell Renton does not have CAAC Approved parts to repair this unit. A CAAC certification (AAC-038) cannot be provided at this time per CCAR-145 R3."

COMPLIED WITH AW/PS REQUIREMENTS.
 THIS COMPONENT IS AIRWORTHY WITH RESPECT TO THE WORK PERFORMED.

PASSED FUNCTIONAL TEST. TEST EQUIPMENT CALIBRATION DATES CHECKED AND FINAL TESTED ON 19 FEB 2018 BY Carl Stephenson

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Repair On Bench		4077865-907	98060341	4077865-907	98060341	1		
Exchange	A10	4058655-2	1384	4058655-2	105	1		

Worn, Dirty, Sticky Keys

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		

RTS TECHNICIAN  _____ DATE FEB 20 2018