



Velocity Aerospace - Burbank, Inc.
 2840 N. Ontario Street
 Burbank, CA 91504
 Ph: 818-246-8431, Fax: 818-246-4322

RECAP
Work Order #: B0324

Date Printed: 7/26/2016
 Time: 2:30:34 PM
 Page: 1

Repair Station: RB1R197K FAA/EASA.145.4002

To: HONEYWELL
 2055 DUBLIN DRIVE
 SAN DIEGO, CA 92154 US

Ship To: HONEYWELL
 Honeywell Int'l Inc.
 1800 W ROSE GARDEN LN
 PHOENIX, AZ 85027

Ref #: 4206855388 Phone #: 619-840-2183 Fax #: Email:
 Mfg: KOITO MFG CO. Serial #: 1787 PN: 83000-05604 Descr: WINDOW HEAT CNTRL

TSN: 0 TSO: 0 TSR: 0

ATA Chapter: 30-40-04 Revision #: 12 Revision Date: 8/18/2014
 Test Record: 2646 Technician: PNGUYEN Type:

Entry Date: 7/19/2016 Need Date: 7/28/2016 Compl. Date: 7/26/2016 2:30:26 PM Container: Warranty: No

Symptoms:

WORKSCOPE: TEST
 REASON FOR REMOVAL
 BENCH TEST
 INSTRUCTIONS: MUST QUOTE

Faults:

NO COMPLAINT GIVEN
 PRELIM TEST & EXAM
 Unit passes F/T.
 Corrective Actions:
 FINAL DISPOSITION: TESTED
 FINAL WORK ACCOMPLISHED
 Performed F/T. Unit passed MFG's test specs.
 TEST EQUIPMENT:
 ABI 575, 1003, 1409, 1482, 1481, 1183, 1606, 1572.

Seq	Task Description	Status
40	<u>PROCURE PARTS FOR WO</u>	PROD - COMPLET
110	<u>INSPECT WO & UNIT</u>	PROD - COMPLET

Final Inspector Signature: Luisito Tuazon