Commercial

Tucson - North Oracle Rd Honeywell International Inc 11100 North Oracle Road TUCSON AZ 85737 Date:10 FEB 2017

Honeywell

Repair Station # HZ3R571L

Initial Findings Report

Repair Order: 2017-327509017-001

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

327548755

Customer P/O: 7358910

Orig Cust:

Part Number: 2119164-3

Part Desc: OUTLINE ELECTRONIC

Serial No: 2119164-00686

CONTROL UNIT

Mods:

Series/Issue/Amdts: 1

Quantity: 1 Aircraft tail#:

Aircraft S/N#:

Date on:

Received Date: 03 FEB 2017 Date off:

Model #: 691 Advanced Controls

Engine S/N:

Alternate S/N:

TIMES/CYCLES

HH.DD (HH:MM)

Time Since New:

Cycles Since New:

Cycles Since Overhaul:

Time Since Repair:

Time Since Overhaul:

Cycles Since Repair:

CUSTOMER REASON FOR RETURN

NONE NOTED

GENERAL CONDITION AS RECEIVED (HIDDEN DAMAGE)

Condition Received Text

AFLE STREET THEOLOGY

Last FT date: 04/03/13

Component review shows normal wear and tear with no visible outer

damage other than noted: dirty, scuffed, touch up

Reason for return code

Removal Type

Not unscheduled(other)

DETAIL DISASSEMBLY / EVALUATION FINDINGS

Failure Description:

Findings:

Related Area:

Non-conformance:

FAILURE

Recurrent Failure:

Failed Part

Part Name

Condition:

Primary Failure

65052350-1

TRANSDUCER ASSEMBLY

4245100-5

CIRCUIT CARD ASSEMBLY, MOTOR DRIVER

Modification suffix missing/incorrect

Modification suffix missing/incorrect

No - but contributing

426-7004-9120

INSULATOR

Worn

No - but contributing

426-016-9013

INSULATOR

Worn SERVICE BULLETINS / AUTHORIZING DOCUMENTS No - but contributing

Authorizing Technical Document

Complied With:

Doc#: SB 2119164-21-4249 Rev: 1 Date: 10/24/2012 Doc#: CMM 21-33-10 Rev: 6 Date: 07/31/2012

WORK PERFORMED / COMMENTS TO CUSTOMER


Workscope Performed / Summary of Actions Taken

Findings: Unit passes Visual, Paint touch-up, scratches etc.

Unit fails Findings per AT2119164, Rev E. Unit fails Motor Altitude Limit Mode.

Needs new Motor Driver board and Mod to Dash 4.

Page: 1 of 2



Commercial

Honeywell

Repair Station # HZ3R571L

Tucson - North Oracle Rd Honeywell International Inc 11100 North Oracle Road **TUCSON AZ 85737**

Date:10 FEB 2017

Configuration And Findings Evaluation

Repair Order: 2017-327509017-001

327548755

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Customer P/O: 7358910

Orig Cust:

Part Number: 2119164-3

Part Desc: OUTLINE ELECTRONIC

CONTROL UNIT

Serial No: 2119164-00686

Mods:

Series/Issue/Amdts: 1

Quantity 1

Ship Date:

Received Date: 03 FEB 2017

Final: Modified to -4. Replaced unserviceable components as described in parts section of CAFE or as listed in Work Accomplished. Unit passed AT2119164 Rev E.

Action Taken Code

Customer Confirmed Removal Reason:

Evaluation Type:

Evaluated - Significant Fault Found

FINAL CONFIGURATION

Part No: 2119164-4

Series/Issues/Amdts: 1

Mods:

MECHANIC/ANALYST Brent Baber

DATE: 06 FEB 2017

Page: 2 of 2

