

Commercial

Honeywell

Repair Station # ZN3R030M

Initial Findings Report

Repair Order: 2017-327758754-001
327805477

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Customer P/O: 7409192

Orig Cust:

Part Number: 3074680-5

Part Desc: FRAME ASSY MN SPRT

Serial No: 0P21406

Mods:

Series/Issue/Amdts:

Quantity: 1

Aircraft tail#:

Model #: TFE Classic

TIMES/CYCLES

Aircraft S/N#:

Engine S/N:

HH.DD (HH:MM)

Date on:

Received Date: 28 FEB 2017

Date off:

Alternate S/N:

Time Since New:

Cycles Since New:

Time Since Overhaul:

Cycles Since Overhaul:

Time Since Repair:

Cycles Since Repair:

CUSTOMER REASON FOR RETURN

Retiring engine

GENERAL CONDITION AS RECEIVED (HIDDEN DAMAGE)

Condition Received Text

Used part Normal condition. This component was removed from engine S/N P101116C.

Reason for return code

Removal Type

Scheduled

DETAIL DISASSEMBLY / EVALUATION FINDINGS

SERVICE BULLETINS / AUTHORIZING DOCUMENTS

Authorizing Technical Document

Complied With:

Doc#: HMM 72-02-71 Rev: 11 Date: 10/01/2008

WORK PERFORMED / COMMENTS TO CUSTOMER

Workscope Performed / Summary of Actions Taken

This component has been inspected to the highest level of the maintenance manual HMM 72-02-71 Rev. 11

Action Taken Code

Overhaul

Customer Confirmed Removal Reason:

Evaluation Type

Evaluated - No Fault Found

Honeywell

Honeywell

Commercial

Honeywell

Repair Station # ZN3R030M

Configuration And Findings Evaluation

Repair Order: 2017-327758754-001
327805477

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Customer P/O: 7409192

Orig Cust:

Part Number: 3074680-5

Part Desc: FRAME ASSY MN SPRT

Serial No: 0P21406

Mods:

Series/Issue/Amdts:

Quantity 1

Ship Date:

Received Date: 28 FEB 2017

FINAL CONFIGURATION

Part No: 3074680-5



S/N: 0P21406



Series/Issues/Amdts:

Mods:

MECHANIC/ANALYST Stephen Kelly

DATE: 01 MAR 2017

Honeywell

Honeywell