

WO # : W358076	R.O. # : 4207937262	TSN :	CSN :	Out Date : 04/30/2018
Customer : HONEYWELL INT'L AEROSPACE	Desc. : SENSOR	TSO : UNK	CSO :	Resp : HT1
Mfg P/N : 0123FA2	S/N : 0471	TSR : UNK	CSR :	Dept : 1110
Org. P/N : 0123FA2	Org. S/N : 0471	TSI :	CSI :	Last WO# :
Mfg Name : GOODRICH SENSORS (ROSEMOUNT)	Spec # :	FH :	FC :	Last Resp :

Malfunction : NONE GIVEN

Instructions : REPAIR

Preliminary (Incoming) Inspection :
P/N and S/N matches the R.O.

Preliminary Functional Test :

Preliminary Functional test Passed

PASSED

Teardown And Inspection Discrepancies Per: GOODRICH, CMM 21-58-02, REV 004

1. 1-1, SENSOR, Cleaning/Inspection Required.
2. All other exposed parts require inspection of defects/damage.

Corrective Action For Previous Discrepancies:

1. S-Inspected and determined to be Serviceable.
2. All other exposed parts were inspected and found serviceable.

Functional Test Results Per : SEE ABOVE REFERENCE

The article functionally tested good

Final Inspection Status :

This article has been inspected, functionally tested and found airworthy. Article is approved for return to service.

Technician

Supervisor

Inspection

HOWARD TOMA

KELLY JASMER

JASON CRANDALL

