



**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street  
Burbank, CA 91504  
Ph: 818-246-8431, Fax: 818-246-4322

Repair Station: RB1R197K FAA/EASA.145.4002

**RECAP**

**Work Order #: D0985**

Date Printed: 3/28/2018

Time: 4:28:51 PM

Page: 1

**To:** HONEYWELL INT'L  
HONEYWELL INTERNATIONAL  
SERVICES SRL (4000)  
POSTAL BRANCH 83, PO BOX 318  
BUCHAREST, ROMANIA

**Ship To:** HONEYWELL INT'L  
C/O HONEYWELL AEROSPACE UK  
UNIT 2 CHEVRON, EATON ROAD  
  
HEMEL HEMPSTEAD HP2 7UB, UNITED  
KINGDOM

Ref #: 4207833799

Phone #:

Fax #:

Email:

Mfg: GOODRICH AEROSPACE

Serial #: 697

PN: 20200-0208

Descr: TANK UNITS

TSN: 0

TSO: 0

TSR: 0

ATA Chapter: 28-41-76

Revision #: 4

Revision Date: 5/8/2017

Test Record: 2642

Technician: SRUNDLE

Type:

Entry Date: 3/15/2018

Need Date: 3/30/2018

Compl. Date: 3/28/2018 4:28:43 PM

Container:

Warranty: No

**Symptoms:**

WORKSCOPE: TEST

REASON FOR REMOVAL

BENCH TEST

**Faults:**

NO COMPLAINT GIVEN

PRELIM TEST & EXAM

Tests in tolerance .

TEARDOWN INSPECTION

Tubes and terminals contaminated w/ fuel residue.

Req. cleaning per CMM and testing .

**Corrective Actions:**

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Cleaned tubes and terminals , F/T to mfgs. specs.

Repaired per CMM 28-41-76 REV 4 DT 05/08/2017

C/W FAA AD 2008-10-10 R1, MOC: Boeing MPD D626A001-CMR, 28-AWL-08

TEST EQUIPMENT:

ABI 1397 , 838

Final Inspector Signature: Luisito Tuazon