



FAA REPAIR STATION 68IR700B
 EASA REFERENCE EASA.145.6295
 2617 EXECUTIVE POINT DR.
 MONROE, NC 28110
 Ph: 704-821-4266 Fax: 704-821-4286
 EMail: quotes@iconaerospace.com

Page 1
WORK ORDER
W77711

Date Rcvd : NOV/14/2017

TEARDOWN REPORT

AERSALE, INC.
 CORPORATE OFFICES
 121 ALHAMBRA PLAZA
 SUITE 1700
 CORAL GABLES, FL 33134

Cust RO#: 10089591
 P/N: 980-6117-004
 S/N: 0412
 Desc: MONITOR, MICROPHONE
 Mfgr: HONEYWELL

Manual Loc: HW-068
 ATA: 23-70-43
 Rev: 7 Rev Date: AUG/23/2002
 Tag Date: DEC/04/2017

Contact: MARIA PEREYRA
 Contact Ph: 469.645.1620 x 6642
 Contact Fax:

Reason Removed: UNIT RECEIVED FOR BENCH CHECK AS PER O.E.M SPEC'S

FINDINGS

RECEIVING INSPECTION:
 VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.
 EN/AC SN: 28507

PRELIMINARY INSPECTIONS:
 TESTED UNIT. FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:
 NONE

CONTINUED INSPECTION:
 DISASSEMBLED UNIT AS REQUIRED AND TESTED. FOUND UNIT CONTAMINATED.

CORRECTIVE ACTION: UNIT CONDITION REPAIRED
 CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

SB's, AD's and RMK's:
 EN/AC SN: 28507

CERTIFICATION

Service Performed: REPAIRED

MODIFIED TO:

PARTS AND MATERIALS

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: Agustin "Gus" Garcia

DATE: DEC/04/2017