

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5008690283 321369791		FAA:	EASA:
PO: 6163040	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	
DATE REJECTED: 02 JUL 2015	DATE RECEIVED: 30 JUN 2015	DATE COMPLETED: 17 JUL 2015	
A/C TYPE:	A/C TAIL NUMBER:	A/C SERIAL NUMBER:	
PACKING STATUS:	SEALS INTACT: Intact	PHYSICAL DAMAGE: NO	
REASON FOR REMOVAL: * 06/30/2015 13:10:46 P. RFC for Celestica CM (ZCELESTICA) * 06/27/2015 11:51:16 Elizabeth Lara (E588483) * PN 1151100-7 SN 069C-0693 * Please test and certify serviceable, repair as required. Dual 8130 tag and service report required. Must comply with group SPOC 008. * Once complete please return unit to HAT-Plant 1013. * * any questions, please contact Elizabeth Lara at 602-436-3304 * ----- * 06/30/2015 13:08:00 Karima Kassam (E605601) * ZRIT ORDER * 06/30/			
PART NUMBER	AS RECEIVED: 1151100-7	AS RELEASED: 1151100-7	
DESCRIPTION:	CONTROLLER AIR SUPPLY AND CABIN PRESSURE	CONTROLLER AIR SUPPLY AND CABIN PRESSURE	
SERIAL NUMBER	069C-0693	069C-0693	
UCN/UID			
HW MOD STATUS:	Series 3M3	Series 3M3	
SW MOD STATUS:			
SOFTWARE LOAD:	3677-GRS-015-00	3677-GRS-015-00	
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed		ESTIMATE SUPPLIED: Yes	
PRIMARY SHOP FINDING: No Fault Found		WARRANTY:	
TYPE OF SERVICE: TESTED		TECHNICIAN: Jedy Huang	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.			
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____			
SIGNATURE OF AUTHORIZED PERSON: _____			
Complied With CMM/Eng Documentation: 36-11-18/12/23-DEC-2011; Service Bulletins: 1151100-36-41/0/01-MAR-2004; Customer Manuals/Documentation:			
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.			

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5008690283		FAA:	EASA:
PO: 6163040	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
 CMM/Eng Documentation:
 Service Bulletins:
 Customer Manuals/Documentation:

Comments:
 Extracted and electronically stored the non-volatile memory and attached the NVM file to the SAP system.

 Unit passed Incoming Functional Test and NO Fault Found.

 Unit passed Final Functional test.

 Unit was loaded with Honeywell Operational Software 1082743-70.

SERVICE BULLETINS / AUTHORIZING DOCUMENTS

Authorizing Technical Documents

Complied With:
 Doc#: ACMM 36-11-18 Rev: 12 Date: 12/23/2011

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed
		1151100-7	069C-0693	1151100-7	069C-0693