

CHROMALLOY

A Division of Chromalloy Gas Turbine LLC
601 Marshall Phelps Road
Windsor, CT 06095 USA
Tel: 860-687-4530 Fax: 860-687-4430
FAA Repair Station TK5R226N

Teardown Report

Customer: HONEYWELL INTERNATIONAL - Pt Date Received: 3/15/2016
Part Number: R* 3061300-3 Customer PO: 3501610480E
Serial No.: 031463100018 CCT Order No.: 92297 1-0
Description: DUCT, UPPER BYPASS CCT Job No.: 111588
Engine: TFE731 Rev 25 Job Quantity: 1
Engine Manual: ATA: 72-IR-02
Engine Man. Rev: 25 Part No. Change:
Man. Rev. Date: 6/22/2007

Workscope

Inspection/Repair	Description of Work
ORI P35157	Repair the fiberglass layer at the forward and/or aft flange areas. Includes painting the forward and aft

Replacement Details

P/N	Description	Qty
-----	-------------	-----

Comments