

Initial Findings Report

Repair Order: 2018-334498709-001
334562947
Customer P/O: 8844356

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Part Number: 967A0000-02

Orig Cust:
Part Desc: MAIN HEAT EXCHANGER

Serial No: 49-815

Mods:

Series/Issue/Amdts:

Quantity: 1

Aircraft tail#:

Model #: Heat Exchanger

TIMES/CYCLES

Time Since New:

Time Since Overhaul:

Time Since Repair:

Time Since Installation:

Aircraft S/N#:

Engine S/N:

HH.DD (HH:MM)

Date on:

Received Date: 10 DEC 2018

Date off:

Alternate S/N:

Cycles Since New:

Cycles Since Overhaul:

Cycles Since Repair:

Cycles Since Installation:

CUSTOMER REASON FOR RETURN

customer request modification to a 967A0000-03

GENERAL CONDITION AS RECEIVED (HIDDEN DAMAGE)

Condition Received Text

UNIT RECEIVED CLEANED PREVIOUSLY CORE REPAIRED AND OVERHAULED

Reason for return code

OTHER, DESCRIBED IN REMARKS

Removal Type

Not unscheduled(other)

DETAIL DISASSEMBLY / EVALUATION FINDINGS

Failure Description:

Findings:

UNIT WAS CLEANED AND PASSED ALL FUNCTIONAL TESTS PER AUTH DOCS, REQUIRES COATING.

Related Area:

Non-conformance: NO CODE AVAILABLE, SEE COMMENTS:

Recurrent Failure:

Failed Part

Part Name

Condition:

Primary Failure

SERVICE BULLETINS / AUTHORIZING DOCUMENTS

Authorizing Technical Document

Complied With:

Doc#: CMM 21-52-26 Rev: 5 Date: 09/10/2018

WORK PERFORMED / COMMENTS TO CUSTOMER

Workscope Performed / Summary of Actions Taken

Unit was cleaned,passed all tests,finald per work instructions and authorizing documents. Unit is Tested.

Action Taken Code

Tested

Customer Confirmed Removal Reason:

Yes

Evaluation Type

Evaluated - No Fault Found

Honeywell

Honeywell

Configuration And Findings Evaluation

Repair Order: 2018-334498709-001
334562947

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Customer P/O: 8844356

Orig Cust:

Part Number: 967A0000-02

Part Desc: MAIN HEAT EXCHANGER

Serial No: 49-815

Mods:

Series/Issue/Amdts:

Quantity 1

Ship Date:

Received Date: 10 DEC 2018

FINAL CONFIGURATION

Part No: 967A0000-02



S/N: 49-815



Series/Issues/Amdts:

Mods:

MECHANIC/ANALYST Jacob Parsons

DATE: 12 DEC 2018

Honeywell

Honeywell