

Repair Station # ZN3R030M

## Initial Findings Report

Repair Order: 2017-330197635-001  
330211231  
Customer P/O: 7938152

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Part Number: 3101783-1  
Orig Cust:  
Part Desc: HOUSING ASSY  
Serial No: 8-08169-2406

Mods:  
Series/Issue/Amdts:  
Quantity: 1  
Aircraft tail#: Aircraft S/N#: Date on: Received Date: 17 OCT 2017  
Model #: Engine S/N: Date off:  
TIMES/CYCLES HH.DD (HH:MM) Alternate S/N:

Time Since New:	Cycles Since New:
Time Since Overhaul:	Cycles Since Overhaul:
Time Since Repair:	Cycles Since Repair:

### CUSTOMER REASON FOR RETURN

Retiring Engine

### GENERAL CONDITION AS RECEIVED (HIDDEN DAMAGE)

#### Condition Received Text

Used part Normal condition.  
This component was removed from engine S/N P-39216C.

#### Reason for return code

Removal Type Scheduled

### DETAIL DISASSEMBLY / EVALUATION FINDINGS

### SERVICE BULLETINS / AUTHORIZING DOCUMENTS

#### Authorizing Technical Document

##### Complied With:

Doc#: IRM 72-IR-10 Rev: 9 Date: 12/22/1995

### WORK PERFORMED / COMMENTS TO CUSTOMER

#### Workscope Performed / Summary of Actions Taken

Stripped paint and refinished complete.  
This component has been inspected to the highest level of the maintenance manual IRM  
72-IR-10 Rev. 09

Action Taken Code Overhaul

#### Customer Confirmed Removal Reason:

Evaluation Type Evaluated - Minor Fault Found

### Configuration And Findings Evaluation

Repair Order: 2017-330197635-001  
330211231

Customer: PLANT1013 HAT - Phoenix Honeywell International Inc.

Customer P/O: 7938152

Orig Cust:

Part Number: 3101783-1

Part Desc: HOUSING ASSY

Serial No: 8-08169-2406

Mods:

Series/Issue/Amdts:

Quantity 1

Ship Date:

Received Date: 17 OCT 2017

### FINAL CONFIGURATION

Part No: 3101783-1



S/N: 8-08169-2406



Series/Issues/Amdts:

Mods:

MECHANIC/ANALYST Stephen Kelly

DATE: 22 OCT 2017