



SHERWOODAVIATION.COM
 PHONE NO: 305-477-2994 4690 N.W. 128TH ST
 FAX NO: 305-477-3367 OPA LOCKA, FL 33054

Work Order: 114757
 Date: March/5/2018
 Phone: 305-477-2994
 Fax: 305-477-3367

TearDown/Inspection Form

Sold To:
 Aviation Spares Int-l. Inc.
 12949 W. Okeechobee Rd. Bay C1 Hialeah Gardens, FL 33018.

Ship To:
 Aviation Spares Int-l. Inc.
 12949 W. Okeechobee Rd. Bay C1 Hialeah Gardens, FL 33018.

Part Number: 622-7998-013 Serial: 4186 Manufacturer: Rockwell Collins
 Description: Display Unit Model: EDU-766D A/C: N/A
 Purchase Order: 00408 Service Performed: Repaired
 Data used: Manual Number: AVI-057A

Teardown/Inspection Data

1.- Reason for Removal: Unknown Inst.: Unit to be Bench Checked and Inspect i/a/w mfg. spec

2. Initial Inspection Findings

Appearance: Normal Corrosion: No corrosion noted
 Loose or Missing Parts: No loose or missing parts Physical Damage: No damaged found

3. Teardown

Dissassembly: As required for repair Cleaning: Cleaned unit
 Painting: None Assembly: As required for repair

4. Test

Operation: Tested I.A.W. MFG Specs Was Complaint Verified: N/A
 Modifications: Mod. form P/N -003 to -013

5. Final

Warranty Accepted: N/A Final Test and Inspection: Final inspection normal
 T.S.O.: N/A A.T.A.: 34-22-60 A.D. S.B. NO A.D. / S. B. # 14

6. Work Performed: Tested, disassembled, and inspected. Unit was cleaned; reconditioned; CRT aligned; S/B 14 applied; assembled, and final tested IAW ATA 34-22-60.


Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the w
 Pertinent details of the work performed are on File at this Agency under Work

Order No.: 114757

Inspector's Name: Ernesto A. Lopez
 Certificate No. 2623565

Technician: Orlando Mazon

Signature: 

Date: March/05/2018

Form CRS-3

Honeywell Honeywell