



Silver Wings Aerospace

FAA # 9ARR711Y
25400 S.W. 140 AVENUE
PRINCETON, FL 33032
Ph: 305-258-5950, Fax: 305-258-5953
sales@silverwingsaerospace.com

Tear Down/Inspection

Work Order #: 308381

Date Printed: 6/26/2018

Page: 1

Customer:

ATTN: Suparada Buck
HONEYWELL AEROSPACE TRADING-PHOENIX
1800 W. ROSE GARDEN LANE
PHOENIX, AZ 85027

Ship To:

HONEYWELL AEROSPACE TRADING-PHOENIX
Honeywell Aerospace Trading (HAT)
1720 E. Grant St., PLANT 1013
Phoenix, AZ 85034

Part Number: 528-70

Description: WING TIP NAVIGATION LIGHT

Serial Number: 2203

Customer R/O: 4207713195

Symptoms:

Customer Request

Work Requested: Bench test.
Discrepancy/Reason for Removal: None reported.

Faults:

Preliminary Inspection

Verified P/N as 528-70 IAW AirPrecision CMM 33-41-12, Revision 6, Revision Date 01/Jan/2006.
Verified S/N as 2203 IAW ID plate and customer's repair order.
Visual Inspection: Damaged Gasket.

Pre-test

Unit failed functional test, tested IAW AirPrecision CMM 33-41-12, Revision 6, Revision Date 01/Jan/2006.
Reason: Lamps and gasket are damaged.
Customer complaint verified: N/A.

Hidden Damages

N/A

Teardown Findings (RP)

Unit partially disassembled to the extent necessary to perform repair.
Cleaned and inspected IAW AirPrecision CMM 33-41-12, Revision 6, Revision Date 01/Jan/2006.
The following parts require replacement: Plate Assy and Lamps.
The following parts require services/rework: N/A.
Condition for the following parts will be determined on final test: N/A.
Honeywell Aerospace has no specialized work instructions.
** Repair Estimate **

AD & SB Status

N/A

Corrective Actions:

Corrective Action

Replaced parts and performed services listed under teardown findings.
Unit assembled and final tested.
The unit was repaired IAW AirPrecision CMM 33-41-12, Revision 6, Revision Date 01/Jan/2006.
Unit comply with Group SPOC 006, Rev: K, Rev Date:01/May/2012.

26 JUN 2018



Silver Wings Aerospace
FAA # 9ARR711Y
25400 S.W. 140 AVENUE
PRINCETON, FL 33032
Ph: 305-258-5950, Fax: 305-258-5953
sales@silverwingsaerospace.com

Tear Down/Inspection

Work Order #: 308381

Date Printed: 6/26/2018

Page: 2

Modifications

N/A

Additional Comments

N/A

Assets

001437, ROF001, 002213.

PN	Description	Qty Issued	CD	Disposition
APF528-111	PLATE ASSY	1	NE	STOCK
CM8-A103	MINIATURE LAMP	2	NE	STOCK

Honeywell

26 JUN 2018