

Interdivisional Purchase Order for Repair (Two Way ZRIT)

Honeywell

Shipper 8005897546

Supplier Cage Code: 07217

Print Date: 18. NOV. 2016

Toronto Contract Mfg Office
Honeywell Limited
3333 Unity Drive
Mississauga ON L5L 3S6



SOLD TO: PLANT9819	Honeywell Aerospace Trading c/o.Honeywell ASCa Inc. 3333 Unity Dr. MISSISSAUGA ON L5L 3S6 CANADA	SHIP TO: PLANT1013	HAT - Phoenix Honeywell International Inc. 1800 W ROSE GARDEN LN PHOENIX AZ 85027 USA
------------------------------	--	------------------------------	---

BILL TO: PLANT1013	HAT - Phoenix Honeywell International Inc. 1800 W ROSE GARDEN LN PHOENIX AZ 85027 USA	MARK FOR:	
------------------------------	---	------------------	--

Freight Forwarder	
--------------------------	--

ORDER INFORMATION		SHIPPING INFORMATION	
Purchase Order No.	7194060	Bill of Lading:	7846 8673 4457
Sales Order No.	TWO-WAY-ZRIT 7194060	Ship Method:	
Contract No.	NONE	Ship Condition:	STO Inter/Intra Co
Vendor Code:		Container Type:	
Currency:	USD	No. of Containers:	0
Incoterms:	EXW SELLER'S FACILITY	Dimensions:	
Payment Terms:	Net 2 Days (Interco)	Gross Weight:	
Sales Office:	2005 - Honeywell Limited	Shipped From:	2131 - Toronto Contract Mfg Office

Item No.	Requested Material No. Honeywell Material No./ Description	Qty	UoM	Serial No./ Lot No.
000010	548376-6 Country of Origin: GB CONTROLLER, CABIN TEMPERATURE PO #: 7194060 001000	1	EA	See add'l info. on the Serial Number Configuration Sheet RECEIVED NOV 28 2016 CT

AW

APPROVED NOV 22 2016

*These items are controlled by the U.S. government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.
End User HAT - Phoenix Ltd. Country of Destination USA

Shipping Instructions:



Contract Representative (If Required)	Date	Government Source Inspection (If Required)	Date
--	-------------	---	-------------

Honeywell certifies that the product (s) describes herein conform to applicable requirements and were procured manufactured or processed in accordance with Honeywell Quality Assurance systems approved by the applicable regulatory authority.

By: FWA
Authorized Signature - Quality Assurance, Honeywell

Serial Number Configuration Sheet

Shipper No. 8005897546

Item No.	Material No.	Serial No.	Rev.	HW Mod	SW Mod
000010	548376-6 	 548376-11289	T		4

Honeywell Honeywell

SERVICE REPORT

ALL NIPPON AIRWAYS CO LTD

SR NUMBER: 5010325431 326438277		FAA:	EASA:
PO: A2046443	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	
DATE REJECTED: 10/17/2016	DATE RECEIVED: 10/17/2016	DATE COMPLETED: 11/03/2016	
A/C TYPE:	A/C TAIL NUMBER: JA02AN	A/C SERIAL NUMBER:	
PACKING STATUS:	SEALS INTACT: Broken	PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: * 10/17/2016 13:31:19 P. RFC for Celestica CM (ZCELESTICA) * 10/17/2016 13:28:59 Karima Kassam (E605601) * REMOVAL REASON * R PACK NO-GO LIGHT ON AT TEMP CONT * BOX-3. (DEAD BAND CHECKING) * SHOP FINDINGS * NFF(NO FAULT FOUND) * ANA REQUIREMENTS: *ANA REQUESTS HONEYWELL TO INVESTIGATE * NUMBER 4-3438519269. * 10/17/2016 13:31:19 P. RFC for Celestica CM (ZCELESTICA) * 10/17/2016 13:28:59 Karima Kassam (E605601) * REMOVAL REASON * R PACK NO-GO LIGHT ON AT TEMP CONT * BOX-3. (DEAD BAND CHECKING)			
PART NUMBER	AS RECEIVED: 548376-6	AS RELEASED: ..	
DESCRIPTION:	CONTROLLER, CABIN TEMPERATURE	CONTROLLER, CABIN TEMPERATURE	
SERIAL NUMBER	548376-11289	548376-11289	
UID(MFR/SPL SER/UCN PNO)			
HW MOD STATUS:	SERIES 3	SERIES 3	
SW MOD STATUS:			
SOFTWARE LOAD:			
REASON FOR REMOVAL CONFIRMED: Rejection Not Confirmed		ESTIMATE SUPPLIED: Yes	
PRIMARY SHOP FINDING: Hardware Fault Found		WARRANTY:	
TYPE OF SERVICE: REPAIRED		TECHNICIAN: Toan Nguyen	
MAINTENANCE STATEMENT: PAGES DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, ARE ATTACHED IN PAGES 2 THROUGH 3			
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____			
SIGNATURE OF AUTHORIZED PERSON: _____			
Complied With CM/Eng Documentation: 76C3404/Rev N/Rev Date 03/14/2000; 21-60-56/Rev 15/Rev Date 10/04/2013; Service Bulletins: Customer Manuals/Documentation:			
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.			

SERVICE REPORT

ALL NIPPON AIRWAYS CO LTD

SR NUMBER: 5010325431		FAA:	EASA:
PO: A2046443	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
 CMH/Eng Documentation:
 Service Bulletins:
 Customer Manuals/Documentation:

Comments:
 External findings:
 Unit coming back with broken seals and unit has been reworked by customer...
 Unit requires fully inspection.
 Unit passed full functional test to A.T.P. with T.D.S.
 Unit has been Examined from G.A. and Engineering.
 Engineering requested for dielectric Test and ESS Burn-In for 02 Cycles.
 Unit has passed Dielectric Test and performed by Johnie Dharandeo from Production Department.
 Unit has also passed ESS Burn-In.
 Unit failed visual inspection:
 A2 CCA has been reworked by customer...C1,C2,C3,C4,C5,C6 requires re-solder.
 A5 CCA: P1 Connector was dirty, requires cleaning.
 Pictures taken.
Repair Action:
 A2 CCA has been reworked.
 A5 CCA: P1 Connector was cleaned.
 Unit passed final test to A.T.P. with T.D.S.

DISPOSITION	REF DSG	P/N	S/N	Installed	P/N	S/N	Removed	Qty	SB
MEASUREMENT DESCRIPTION									
MEAS. VALUE (DECIMAL)									
MEAS. VALUE (HH:MM)									
TIME SINCE REPAIR									
0:00									

SERVICE REPORT

ALL NIPPON AIRWAYS CO LTD

SR NUMBER: 5010325431		FAA:	EASA:
PO: A2066473		CONTRACT NUMBER:	
CUSTOMER PART NUMBER:		MEAS. VALUE (HH:MM):	
MEASUREMENT DESCRIPTION		MEAS. VALUE (DECIMAL):	
CYCLES SINCE REPAIR			

